• •		CUNTIDEN SCHOOL INFOR	MATION	0 0	255
" ALITIE	CLASSIFII C	CATION SECRET/CONTROL - I		ICIALS C REPOR	
		ORMATION REPO		CD NO.	50X1-HUM
COUNTRY	Germany (Russian Z	one)		DATE DISTR.	16 October 1951
SUBJECT	Information on Rus	sian Zone		NO. OF PAGES	2
	Railroad Repair Sh	òps		NO. OF ENCLS.	50// 11/14
PLACE ACQUIRED			ī	(LISTED BELOW)	50X1-HUM
NFO.					
			1		
was nogeneral	CONTAINS INFORMATION APPROXISE THE	TATIONAL BEFENCE			
D. S. C. SI AND	Convains infomention apparatus of the a states within the meaning of the a se, as emerged. Its transcription of 19 in any manner to are upanthorized reproduction of this form is pre-	THE REVELATION A THIS	IS UNEV	ALUATED INFORMA	TION
					50X1-HUM
				•	
to the following causes:  a. The former Corman Treight cars returned from the U.S.S poor condition and their repair requires more working than anticipated.					ttributed in a vory ad material
	b. Important row materials required cannot be obtained in the Soviet Zone of Cermany and deliveries from the West have been stopped. Structural steel for freight cars, nedium sheets for locomotives, high quality steels and non-ferrous metals, and ingot iron in particular, are in short supply.  c. More than 100 heavy motors of S-Bahn cars were stored at the Berlin-Schoeneweide railroad repair shop. These rotors cannot be repaired since guttagercha, high quality strands (Litze), coils (Micklungen) and ball bearings are not available. *				
2	railroad repair shop, his deputy Sohr (fnu), and four other employees of this installation were arrested. The chairman of the workers connittee of the railroad repair shop was discharged without any notice. It was stated that the arrest of the employees mentioned was due to expenditures in excess of the budget allocated to the Potsdam railroad repair shop. A Czech was made technical manager of the railroad repair shop. ***				
	Comment. Railroad repair shops in the Berlin railroad district include the Berlin-Marschauerstrasse, Berlin-Schoeneweide, Berlin-Tempelhof, Berlin-Grunevald, Potsdam and Brandenburg-West railroad repair shops. The production quotas allocated to these repair shops for 1951 were seported previously. The former German freight cars returned from the U.S.S.R. referred to are 50X1-HUM the 20,000 cars returned since 1 June 1951.  of these cars are damaged and can be used again only after extensive repair of these cars are damaged and can be used again only after extensive repair everk performed in railroad repair shops. The Berlin-Schoeneweide railroad repair shop specializes on the repair of railroad cars used for the electrified repair shop specializes on the repair of railroad cars used for the electrified service interurban railroad system.  SECURITY INFORMATION  ONLY				
STATE	CLASSI	The second secon	U.S. OF	TULALS UNLI	A 1 - 100 (1) (100 to 1) (1)
ARMY	# F AIR # 1 FB		AL	Charge in election     Declaration	0
				i i sa	

Sanitized Copy Approved for Release 2011/04/20: CIA-RDP82-00457R008700230008-0

SECRET/CONTROL - U.S. OFFICIALS ONLY

CENTRAL INTELLIGENCE AGENCY

\*\* Comment. Sohr was previously known as the deputy technical director 50X1-HUM of the Potsdam railroad repair shop. Schroeder is reported for the first time. It has previously been thought that one Kochner was technical director of the Potsdam repair shop.

50X1-HUM

ECRET/COUTROL/US OFFICIALS ONLY